

## UPDATE: ABOUT YOUR MACINTOSH LC II

### Logic Board Upgrade

Your computer has been upgraded to the Macintosh LC II. It is recommended that you use version 7.0.1 of system software, provided with your upgrade kit. Information about using version 7.0.1 is described in the manuals that came with the upgrade kit. If you are currently running version 6.0.8 and do not wish to upgrade your system software, keep the manuals that came with your computer. (It is not recommended, however, that you use versions 6.0.7 or 7.0. Your Macintosh LC II may experience problems.)

This update describes only those hardware changes to your LC that result from your upgrade.

### Processor

- MC68030, 32-bit architecture, 15.6672 megahertz (MHz) clock frequency (includes built-in memory management unit), provides internal connector for an optional floating-point unit (FPU)

!! WARNING: If you have an FPU on the main logic board of your LC II, do not install an expansion card that also contains one. If you have two FPUs, your LC II may not work properly. !!